SECTION 3.10 - Each Journeyman shall be required to furnish a minimum kit of tools necessary to perform his classification of work. The following shall be considered a minimum tool list for a Journeyman Inside Wireman:

2 pr. channel lock type pliers 1 pr. 8" or 9" cutter pliers 1 pr. 6" or 7" diagonal cutter pliers 1 pr. needle nose pliers 1 pipe wrench-14" or small chain tongs 1 adjustable 10" wrench 1 screwdriver, stubby 1 screwdriver, 3" blade 1 screwdriver, 5" blade 1 screwdriver, 8" blade 1 Phillips screwdriver, size 1 & 2 2 cold chisels, 1/2" & 1" 1 hack saw frame, adjustable 1 center punch 1 folding rule - 6' 1 tool box 1 scratch awl 1 combination square - 12" 1 leather tool pouch Pencils * 1 key hole saw

1 set spin tite wrenches - 3/16", 5/16", 11/32", 3/8", 7/16"&1/2" 1 set Allen wrenches, up to and including 3/8" size 1 set wrenches; open end, box socket or adjustable to 1" 1 wire skinning pocket knife 1 level, 9" or 12" 1 tap wrench, up to 1/4" 1 pr. airplane shears, 10" straight cut 1 ¾" wood chisel 1 voltage tester-induction type (not neon or incandescent) 1 chalk line 1 flashlight (batteries furnished by Employer) 1 plumb bob 1 claw hammer Safe working shoes

* 1 set of taps-#6/32, #8/32, #10/24, ½ - 20

* 1 set of drills, 1/8", 5/32", 3/16", 7/32", 9/32", 3/8", #36, #29, #25, #7

The Employer shall furnish all wrenches of any description, 16" or more in length, hack saw blades, cutting tools, bits, special tools of any kind and other necessary tools and equipment, including facilities for delivering Employers tools and materials to the job site.

The Employer shall also provide a safe place for storage of all tools including the employee's personal tools. Workmen shall be responsible for pick up and storing of the tools and/or equipment.

Workmen shall move personal tools, after 4:30 p.m., to next job site for the following day, if notified before 4:30 p.m.

^{*} Broken or worn cutting tools starred are to be replaced by Employer.